COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

I. IDENTIFICATION

1. Resource number:

5BL961.1

2. Temporary number:

N/A

3. County:

Boulder

4. City:

Louisville

Historic building name:

Stolns House

6. Current building name:

Chavez House

7. Building address:

616 Front Street

8. Owner name:

Virginia K. Chavez

Owner address:

600 Front Street

Louisville, CO 80027

II. GEOGRAPHIC INFORMATION

9. P.M. 6th Township 1S Range NE% of NW% of SE% of SE% of section 8

10. UTM reference

Zone 13

Easting:

488870

Northing: 4424930

11. USGS quad name: Louisville, Colorado

Year: 1965 (Revised 1994) 7.5'

12. Lot(s): 4, 5 Block:

completed April Addition: Original Town of Louisville Year of Addition1878

13. Boundary Description and Justification: This legally defined parcel encompasses but does not exceed the land historically associated with this property.

Official Eligibility Determination

(OAHP use only)

Date			IIIIIIais		
	Determined	Eligible	- 1	National	Registe

Determined Not Eligible - National Register

Determined Eligible - State Register

Determined Not Eligible - State Register

Needs Data

Contributes to eligible National Register District

Noncontributing to eligible National Register District

ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape):

L-Shaped Plan

15. Dimensions in feet: 682 square feet

16. Number of stories:

17. Primary external wall material

Wood / Weatherboard

18. Roof configuration (enter one):

Cross Gabled Roof

Primary external roof material (enter one):

Asphalt Roof

Special features (enter all that apply):

Porch

Chimney

Fence

22. Architectural style / building type:

Other Style (wood frame cross gabled dwelling)



Temporary Resource Number: N/A

Architectural Inventory Form

(Page 2 of 5)

21. General Architectural Description

The house at 616 Front Street is supported by a low concrete foundation, and features painted yellow horizontal weatherboard walls, with 1" by 4" cornerboards. The cross gabled roof is covered with brown asphalt shingles, and has painted white boxed eaves. A brick chimney is located on the ridge. Window patterns include 2/2 double hung sash, 4/4 double hung sash, and 2-light hoppers, all with painted white wood frames and surrounds. Located on the west elevation, the house's primary entry features a painted white wood-paneled door with two upper sash lights with rounded tops. This door, accompanied by a painted black wood screen door, opens onto a concrete shed-roofed porch, with a painted yellow 4" by 4" wood post. Another wood-paneled door. located at the south end of the facade, features carved sunburst motifs in its panels, egg-and-dart molding, and a single light in its upper sash. An 18' by 6' shed-roofed extension to the east (rear) elevation features 1x1 horizontal sliding windows. A painted white wood-paneled door, with a glass-in-steel frame storm door, opens from the addition onto a concrete, shed-roofed porch, on the east elevation.

29.Construction History (include description and dates of major additions, alterations, or demolitions:

Sanborn Map Company maps, from 1893, 1900, and 1908, provide evidence that this house was constructed prior to 1893, and that there have been no additions to the original structure.

23. Landscape or setting special features:

This house is located on the east side of Front Street, south of downtown Louisville. A planted grass front yard to the west, features twin cedar trees, and is enclosed by a chain link fence. Planted grass back and side yards, to the east, north and south, are enclosed by a wood privacy fence.

24. Associated buildings, features, or objects n/α

IV. ARCHITECTURAL HISTORY

Date of Construction:
Estimate cα. 1890
Actual

Source of information: Sanborn map, 1893

26. Architect:

n/a

Source of information:

n/a

27. Builder/ Contractor:

unknown

Source of information:

n/a

n/a

28. Original owner:

unknown

Source of information:

30. Original location: yes

Moved no Date of move(s) n/α

Temporary Resource Number: N/A

Architectural Inventory Form

(Page 3 of 5)

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Sing

Single Dwelling

32. Intermediate use(s): Single Dwelling

33. Current use(s):

Single Dwelling

34. Site type(s):

Residence

35. Historical Background

According to Sanborn maps, prepared for fire insurance purposes in 1893, 1900, and 1908, this house was constructed in the years prior to 1893, and has not been built onto since that time. In the 1940s, and probably in earlier years, this was the home of the Stolns family. Members of the Stolns family living here in 1940, according to that year's Boulder County Directory, included Lewis B. Stolns, his wife Anna B. Stolns, along with Edwin, and Julius Stolns. Lewis and Edwin are both listed in the directory as laborers. In the late 1950s the property was sold by Elsie M. Stolns to Solomon S. and Mary P. Duran. Solomon's occupation is also listed as laborer. According to Boulder County Directories, and later Longmont City Directories, the property stayed in the Duran family until the early 1990s. (Listings for Louisville are included in Boulder County Directories through the late 1950s; beginning in 1966, Louisville listings appear in Longmont City Directories.) Solomon Duran evidently passed away in the early 1970s. Mary Duran lived here until the early 1990s. In recent years, in the mid-to-late 1990s, this property has been owned by Virginia Chavez. She lives next door at 600 Front Street. (The Duran name occasionally is misspelled "Dauran" in the Longmont City Directories.)

36. Sources of Information

(Boulder County) "Real Estate Appraisal Card - Urban Master", on file at the Boulder Carnegie Library.

Conarroe, Carolyn. The Louisville Story, Louisville: Louisville Times Inc., 1978.

Chavez, Virginia. Oral interview with Carl McWilliams, January 13, 2000.

Polk's Boulder County Directory [generally published annually], Denver, Kansas City, and Salt Lake City: R.L. Polk and Company Publishers.

Polk's Longmont City Directory, [generally published annually], Denver, Kansas City, and Salt Lake City: R.L. Polk and Company, Publishers, 1966 - 1997.

Sanborn Fire Insurance Maps, dated August 1893, November 1900, and August 1908.

Smith, Phyliss. Once A Coal Miner: The Story of Colorado's Northern Coal Field, Boulder: Pruett Publishing Company, 1989.

Temporary Resource Number: N/A

Architectural Inventory Form

(Page 4 of 5)

VI. SIGNIFICANCE

37. Local landmark designation:

Yes

No xx

Date of Designation: n/a

- 38. Applicable National Register Criteria
- xx A. Associated with events that have made a significant contribution to the broad patterns of our history;
 - B. Associated with the lives of persons significant in our past;
- xx C. Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction;
 - D. Has yielded, or may be likely to yield information important in history or prehistory;

Qualifies under Criteria Considerations A through G (see Manual).

Does not meet any of the above National Register criteria.

39. Area(s) of Significance:

Community Planning and Development; Ethnic Heritage - European

- 40. Period of Significance: ca. 1890-1950
- 41. Level of Significance:

National:

State:

Local:

xx

42. Statement of Significance

Built circa 1890, this small residence is historically and architecturally significant for its association with Louisville's early development as a coal mining community. Platted in 1878, and incorporated four years later, Louisville evolved as a result of the effort to extract coal from Colorado's northern coal field. From the late 1870s until the mid-1950s, Louisville's socioeconomic development was closely aligned with the coal mining industry. Early owners and residents of this house undoubtedly worked at area coal mines. Architecturally, this house is a good local example of a relatively unaltered wood frame cross gabled dwelling dating from before the turn of the twentieth century.

43. Assessment of historic physical integrity related to significance:

This house displays an overall high degree of historical integrity. There have been no additions subsequent to the original construction. Alterations to the dwelling, including a shed-roofed patio to the east (rear) elevation, are minimal.

Temporary Resource Number: N/A

Architectural Inventory Form

(Page 5 of 5)

NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility field assessment:

Eligible: XX

Not Eligible:

Need Data:

45. Is there National Register district potential?

Yes:

No:

Discuss:

Houses and other buildings in this area southeast of downtown Louisville, do not collectively display sufficient historical integrity to qualify as a National Register Historic District.

If there is National Register district potential, is this building:

Contributing:

n/a

Noncontributing:

n/a

46. If the building is in an existing National Register district, is it:

Contributing:

Noncontributing:

n/a

VIII. RECORDING INFORMATION

47. Photograph numbers:

Roll:

CM-6

Frame(s): 33-36

Negatives filed at: City of Louisville, Administration

749 Main Street

Louisville, Colorado 80027

Report title: "Old Town" Louisville Historical Building Survey 48.

49. Date: January 13, 2000

50. Recorder(s): Carl McWilliams


51. Organization: **Cultural Resource Historians**


52. Address:

1607 Dogwood Court

Fort Collins, Colorado 80525

Phone number: 970/493-5270 53.





LOCATION MAP



