COLORADO CULTURAL RESOURCE SURVEY

Architectural Inventory Form

(Page 1 of 5)

I. IDENTIFICATION

1. Resource number:

5BL935

2. Temporary number:

N/A

3. County:

Boulder

4. City:

Louisville

5. Historic building name: Ostrander House; Lawrence House

6. Current building name: Dunlap House

7. Building address:

741 Lincoln Avenue

8. Owner name:

Gary H. Dunlap

Owner address:

741 Lincoln Avenue

Louisville, CO 80027

II. GEOGRAPHIC INFORMATION

9. P.M. 6th Township 1S Range 69W NW% of SW% of NW% of SE% of section 8

10. UTM reference

Zone 13

Easting: 488350

Northing: 4425100

Year:

Addition: Pleasant Hill

Year of Addition 1900

13. Boundary Description and Justification: This legally defined parcel encompasses but does not exceed the land historically associated with this property.

orado

or 11. USGS quad name: Louisville, Colorado 1965 (Revised 1994) 7.5' 12. Lot(s): 1-4 Block:

Official Eligibility Determination

(OAHP use only)	
Date	Initials
Determined Eligible - National Register	
Determined Not Eligible - National Register	
Determined Eligible - State Register	
Determined Not Eligible - State Register	
Needs Data	
Contributes to eligible National Register District	
Noncontributing to eligible National Register District	

ARCHITECTURAL DESCRIPTION

14. Building plan (footprint, shape):

L-Shaped Plan

15. Dimensions in feet: 1405 square feet


16. Number of stories:

17. Primary external wall material

Brick

22. Architectural style / building type:

Other Style (Brick Masonry Gabled L Dwelling)



Temporary Resource Number: N/A

Architectural Inventory Form

(Page 2 of 5)

21. General Architectural Description

One of Louisville's few examples of a historic brick residence, this 11/2story dwelling is set on a low coursed sandstone foundation. The exterior walls are red brick, laid in common bond (headers every seventh course), and there are three belt courses, described as follows: two rows of projecting stretchers form a belt course at the level of the first story window sills; two rows of projecting stretchers, separated by a course of bricks laid in a sawtooth pattern, creates a belt course at the level of the first story window lintels; the third belt course is formed by two courses of projecting stretchers, at the level of the upper half story window sills. The building is covered by a cross gabled roof, with grey asphalt shingles and boxed eaves. A red brick chimney is located on the exterior of the south elevation. Window patterns are predominantly 3/1 double-hung sash (ribbon style), with transom lights, painted white wood frames, stone lugsills, and segmental brick arch headers. A stained natural brown wood-paneled front entry door, with a stained glass upper sash light, and with decorative carved panels, and with a dentil course in the locking rail, is located on the east elevation. This door has a distinctive, painted white, wood screen door, and opens onto a painted red tongue-and-groove wood porch, located at the north end of the facade (east elevation). The porch has painted buff red concrete half walls, and painted white turned columns, with brackets, supporting a hipped and gabled porch roof. A wood frieze appears along the roof eave. A 10-light glass-in-wood-frame door, with flanking sidelights, opens onto a concrete patio, covered by a flat roof balcony, on the west elevation. This roof also serves as an upper half-story balcony. A painted white wood door, with a segmental brick arch header, opens onto the balcony.

A Carriage House, or Garage, is located west of the house. This 11/2-story brick building is supported by a concrete foundation, and has red brick walls, laid in common bond. Painted beige square-cut wood shingles appear in the upper gable ends. The roof is a steeply-pitched side-gable, with a short shed-roofed extension to the north. A gabled wall dormer, with two single-light windows, topped by clerestory windows, are located on the south elevation. 1/1 double-hung sash windows are located in the upper gable ends, on the west and east elevations. A large metal rollaway garage door opens onto a concrete driveway which extends to Spruce Street to the north.

29.Construction History (include description and dates of major additions, alterations, or demolitions:

Boulder County Assessor records indicate that this building was constructed in 1905. This date is plausible given the house's architectural character, and that the Pleasant Hill Addition was platted in 1900. A wood-frame, shed-roofed addition, to the north end of the west elevation, appears to be more than fifty years old. The Carriage House appears to date from the period of significance.

23. Landscape or setting special features:

This property is located at the southwest corner of Lincoln Avenue and Spruce Street, in an older residential neighborhood west of downtown Louisville. A large planted grass side yard to the south, and a small back yard to the west, are enclosed by a wrought iron fence which parallels Lincoln Avenue, and by a woven wire fence along the south property line. irrigation ditch runs behind the property, along the north property line. There is no alley.

24. Associated buildings, features, or objects Carriage House/ Garage

IV. ARCHITECTURAL HISTORY

Date of Construction: Estimate

Actual 1905

Source of information: **Boulder County Assessor Records**

26. Architect:

n/a

Source of information:

27. Builder/ Contractor:

unknown

Source of information:

na

Original owner:

unknown

Source of information:

n/a

Original location: Moved

Date of move(s)

Temporary Resource Number:

Architectural Inventory Form

(Page 3 of 5)

V. HISTORICAL ASSOCIATIONS

31. Original use(s): Single Dwelling

Intermediate use(s): Single Dwelling 32.

33. Current use(s): Single Dwelling

Site type(s):

Residence

35. Historical Background

This house was constructed a few years after the turn of the twentieth century, and has served as a single-family dwelling since that time. Little is known about the early residents and owners of this property. There is a good chance, though, that they were employed by area coal mines. During the late 1800s and early 1900s, Louisville's economy was principally based on the area's coal industry, and consequently, the livelihoods of most of the community's inhabitants were directly, or indirectly, dependent on the coal mines.

By the late 1920s (and perhaps earlier), this house had become the residence of Albert (Bert) H. and Mabel Ostrander. Having come to Louisville in the years prior to 1904, the Ostranders ran a bakery. They previously resided at 945 Spruce Street. Other members of the Ostrander family - Othello R. and Isabelle Ostrander - resided at 240 Lincoln Avenue. Othello Ostrander was employed as a laborer in the 1910s. Albert Ostrander passed away in the late 1940s, but Mabel, his widow, continued to reside in this house until the early-to-mid-1950s.

In the late 1950s, this was the home of Norris W. and Janice H. Olson. Mr. Olson was employed at Wards. In the early 1960s, this property was acquired by Leonard B. and Clara M. Lawrence. The Lawrences, who had previously resided at 564 Lincoln Avenue, lived here until the early 1990s. The property's current owner and resident is Gary Dunlap. He has lived here since 1994.

36. Sources of Information

(Boulder County) "Real Estate Appraisal Card - Urban Master", on file at the Boulder Carnegie Library.

Polk's Boulder County Directory [generally published annually], Denver, Kansas City, and Salt Lake City: R.L. Polk and Company Publishers.

Polk's Longmont City Directory, [generally published annually], Denver, Kansas City, and Salt Lake City: R.L. Polk and Company, Publishers, 1966 - 1997.

Conarroe, Carolyn. The Louisville Story, Louisville: Louisville Times Inc., 1978.

Temporary Resource Number: N/A

Architectural Inventory Form

(Page 4 of 5)

VI. SIGNIFICANCE

37. Local landmark designation:

Yes

No xx

Date of Designation: n/a

- 38. Applicable National Register Criteria
- xx A. Associated with events that have made a significant contribution to the broad patterns of our history;
 - B. Associated with the lives of persons significant in our past;
- Embodies the distinctive characteristics of a type, period, or method of construction, or represents the work of a master, or that possess high artistic values, or represents a significant and distinguishable entity whose components may lack individual distinction;
 - D. Has yielded, or may be likely to yield information important in history or prehistory;

Qualifies under Criteria Considerations A through G (see Manual).

Does not meet any of the above National Register criteria.

39. Area(s) of Significance:

Architecture: Community Planning and Development

- 40. Period of Significance: 1905 1950
- 41. Level of Significance:

National:

State:

Local: xx

42. Statement of Significance

This house is historically significant, relative to National Register Criterion A, for its association with residential development in Louisville during the first half of the twentieth century. The house is architecturally significant, under National Register Criterion C, as a relatively rare brick residence in Louisville.

43. Assessment of historic physical integrity related to significance:

This house displays an overall high degree of historical integrity. There have been no additions, and no overt alterations, within the past fifty years. The Carriage House, is also contributes to the property's sense of historical significance, although its upper half story appears to have been altered.

Temporary Resource Number: N/A

Architectural Inventory Form

(Page 5 of 5)

VII. NATIONAL REGISTER ELIGIBILITY ASSESSMENT

44. National Register eligibility field assessment:

Eligible: xx Not Eligible: Need Data:

45. Is there National Register district potential?

Yes:

xx

No:

Discuss:

Historic buildings in this neighborhood, that have retained a sufficient measure of their integrity, may have the potential to comprise a National Register historic district.

If there is National Register district potential, is this building:

Contributing:

xx

Noncontributing:

46. If the building is in an existing National Register district, is it:

Contributing:

 n/α

Noncontributing:

 n/α

VIII. RECORDING INFORMATION

47. Photograph numbers:

Roll: **CM-7** Frame(s): **24-28**

Negatives filed at: City of Louisville, Administration

749 Main Street

Louisville, Colorado 80027

48. Report title: "Old Town" Louisville Historical Building Survey

49. Date: April 5, 2000

50. Recorder(s): Carl McWilliams


51. Organization: Cultural Resource Historians

52. Address: 1607 Dogwood Court

Fort Collins, Colorado 80525

53. Phone number: 970/493-5270


Spruce Street



Lincoln Avenue

Approximate
Scale
40 Feet

SKETCH MAP



LOCATION MAP







741 Lincoln Avenue



